



Trunk group number	Trunk group name	Equipment ID	Group direction	Sub-route		OPC	DPC	Call source code	Call source name	Circuit type
				number	Sub-route name					
30	LITA	172.23.14.130:2944	INOUT(Bi-directional trunk)	30	LITA	901	000A20	20	REGION_06	ISUP
118	EJNC	172.23.14.130:2944	INOUT(Bi-directional trunk)	118	JUNCAL	901	000A73	20	REGION_06	ISUP
120	MARA	172.23.14.130:2944	INOUT(Bi-directional trunk)	120	MAR_ACOSTA	901	000A74	20	REGION_06	ISUP
121	PBNV	172.23.14.130:2944	INOUT(Bi-directional trunk)	121	PUEBLO NUEVO	901	000A77	20	REGION_06	ISUP
124	LCPC	172.23.14.130:2944	INOUT(Bi-directional trunk)	124	LA CONCEPCION	901	8,00E+04	20	REGION_06	ISUP
125	GRMR	172.23.14.130:2944	INOUT(Bi-directional trunk)	125	GARCIA MORENO	901	000A56	20	REGION_06	ISUP
126	ECML	172.23.14.130:2944	INOUT(Bi-directional trunk)	126	CARMELO	901	0008A8	20	REGION_06	ISUP
127	PSFC	172.23.14.130:2944	INOUT(Bi-directional trunk)	127	PLAYON SN FRAN	901	000C34	20	REGION_06	ISUP
128	GZPZ	172.23.14.130:2944	INOUT(Bi-directional trunk)	128	GONZ_PIZARRO	901	000C38	20	REGION_06	ISUP
129	SCEL	172.23.14.130:2944	INOUT(Bi-directional trunk)	129	SANTA CECILIA	901	000C20	20	REGION_06	ISUP
131	TULC	172.23.14.130:2944	INOUT(Bi-directional trunk)	131	TULCAN	901	001A02	20	REGION_06	ISUP
132	PARN	172.23.14.130:2944	INOUT(Bi-directional trunk)	132	PABLO ARENAS	901	000A7D	20	REGION_06	ISUP
133	GFAR	172.23.14.130:2944	INOUT(Bi-directional trunk)	133	GENERAL FARFAN	901	000C14	20	REGION_06	ISUP
134	CAHS	172.23.14.130:2944	INOUT(Bi-directional trunk)	134	CAHUASQUI	901	000A79	20	REGION_06	ISUP
135	IMTG	172.23.14.130:2944	INOUT(Bi-directional trunk)	135	IMANTAG	901	000A54	20	REGION_06	ISUP
138	AZMA	172.23.14.130:2944	INOUT(Bi-directional trunk)	138	AZAMA	901	000A5A	20	REGION_06	ISUP
139	GLSQ	172.23.14.130:2944	INOUT(Bi-directional trunk)	139	GUALSAQUI	901	000A5C	20	REGION_06	ISUP
140	ELEN	172.23.14.130:2944	INOUT(Bi-directional trunk)	140	EL ENO	901	000C12	20	REGION_06	ISUP
141	SFBJ	172.23.14.130:2944	INOUT(Bi-directional trunk)	141	SN FRAN BORJA	901	000CE8	20	REGION_06	ISUP
143	SPDC	172.23.14.130:2944	INOUT(Bi-directional trunk)	143	SN PEDRO COFA	901	000C5C	20	REGION_06	ISUP
144	CJAT	172.23.14.130:2944	INOUT(Bi-directional trunk)	144	AROSEMENA TOLA	901	000C90	20	REGION_06	ISUP
145	ILUM	172.23.14.130:2944	INOUT(Bi-directional trunk)	145	ILUMAN	901	000A63	20	REGION_06	ISUP
149	OTVL	172.23.14.130:2944	INOUT(Bi-directional trunk)	149	OTAVALO	901	000A58	20	REGION_06	ISUP
154	IBR2	172.23.14.130:2944	INOUT(Bi-directional trunk)	154	TDI	901	001A81	20	REGION_06	ISUP
272	ATUQ	172.23.14.130:2944	INOUT(Bi-directional trunk)	270	ATUNTAQUI	901	001AC0	20	REGION_06	ISUP
273	IBR1	172.23.14.130:2944	INOUT(Bi-directional trunk)	271	IBARRA1	901	001A90	20	REGION_06	ISUP
828	ECHT	172.23.14.130:2944	INOUT(Bi-directional trunk)	828	El Chota	901	000A72	20	REGION_06	ISUP